



International Association of Penturners

Bandsaw Segmenting Jig


Author: Ken Burgess aka: KenB259 DATE, July 2020

Downloaded from www.penturners.org

*To build the jig and attachments see attached prints



Jig table



"L" Bracket




Stop



Pivot Point

1

The Jig is stationary, clamp to the band saw.



Saw blade is centered in hole.

2

Place "T" bolt in T-track on the right side.
Place Pivot Point over the bolt.



Slide "L" Bracket over Pivot Point add
a washer and secure with a wing nut.

3

Slide to the position you select.
Place stop at a position you select.
(left side T-track is for the stop).



4

Clamp the blank to the "L" bracket.



Options:

- *Use spacers for placement.*
- *It's possible to use the "L" bracket on the left side for a pivot point.*
- *Experiment with so many different ways.*



